



SGS Canada Inc.

P.O. Box 4300 - 185 Concession St. Lakefield - Ontario - KOL 2H0 Phone: 705-652-2000 FAX: 705-652-6365

15-October-2013

OCWA-Trent Valley (Quinte Mohawk School)

Attn : James Taylor

Date Rec. : 08 October 2013 LR Report: CA14261-OCT13

Box 20157, 131 St. Paul St. Belleville, ON K8N 5V1,

Copy: #1

Phone: 613-962-5454 Fax:pdf-ID Plant

CERTIFICATE OF ANALYSIS Final Report

Table with 11 columns: Analysis, 1: Analysis Start Date, 2: Analysis Start Time, 3: Analysis Approval Date, 4: Analysis Approval Time, 5: MAC, 6: Half MAC, 7: AO/OG, 8: MDL, 9: NR/TW QMS 1ec6a Treated Water, 10: NR/DW QMS Staff Room Tap. Rows include various chemical and physical parameters like Temperature, pH, Chlorine, Sulphide, etc.


SGS Canada Inc.

P.O. Box 4300 - 185 Concession St.
Lakefield - Ontario - K0L 2H0
Phone: 705-652-2000 FAX: 705-652-6365

Project : PO#017018

LR Report : CA14261-OCT13

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.
MAC - Maximum Acceptable Concentration
Half MAC - Half of the Maximum Acceptable Concentration
AO/OG - Aesthetic Objective / Operational Guideline
MDL - SGS Method Detection Limit
*Sodium > 20mg/L is an indicator of adverse water quality.



Carrie Greenlaw
Carrie Greenlaw
Project Specialist
Environmental Services, Analytical