

SGS Canada Inc.

P.O. Box 4300 - 185 Concession St.
Lakefield - Ontario - K0L 2H0
Phone: 705-652-2000 FAX: 705-652-6365

21-May-2014

OCWA-Trent Valley (Quinte Mohawk School)

Attn : James Taylor

Date Rec. : 13 May 2014

LR Report: CA15160-MAY14

Box 20157, 131 St. Paul St.
Belleville, ON
K8N 5V1,

Copy: #1


Phone: 613-962-5454
Fax:pdf-ID Plant

CERTIFICATE OF ANALYSIS

Final Report

Sample ID	Sample Date & Time	Temperature Upon Receipt °C	Field pH	Alkalinity mg/L as CaCO3	Lead ug/L
1: Analysis Start Date		---	---	15-May-14	20-May-14
2: Analysis Start Time		---	---	10:40	13:09
3: Analysis Approval Date		---	---	16-May-14	21-May-14
4: Analysis Approval Time		---	---	15:49	09:58
5: MAC		---	---	---	10
6: AO/OG		---	---	30-500	---
7: MDL		---	---	2	0.01
8: 1EC6A NR/DW Sink Staff Room Sink 1st	12-May-14 08:25	16.0	7.3	333	0.28
9: 1EC6A NR/DW Sink Staff Room Sink 2nd	12-May-14 08:55	16.0	7.4	331	0.27
10: 6712 NR/DW Sink Daycare Sink 1st	12-May-14 08:35	16.0	7.4	333	0.28
11: 6712 NR/DW Sink Daycare Sink 2nd	12-May-14 09:05	16.0	7.5	334	0.26

Field pH was not analyzed by SGS Environmental Services.
MAC - Maximum Acceptable Concentration
AO/OG - Aesthetic Objective / Operational Guideline
MDL - SGS Method Detection Limit



Carrie Greenlaw
Project Specialist
Environmental Services, Analytical