



**SGS Canada Inc.**

P.O. Box 4300 - 185 Concession St.  
Lakefield - Ontario - KOL 2H0  
Phone: 705-652-2000 FAX: 705-652-6365

Not Reportable as per Chain of Custody  
Works #: 1156

Project : PO#017018

03-April-2014

**OCWA-Trent Valley (Quinte Mohawk School)**

Attn : James Taylor

Date Rec. : 01 April 2014

LR Report: CA16077-APR14

Box 20157, 131 St. Paul St.  
Belleville, ON  
K8N 5V1,

Copy: #1

Phone: 613-962-5454  
Fax:pdf-ID Plant

# CERTIFICATE OF ANALYSIS

## Final Report

Sample ID	Sample Date & Temperature Time	Temperature Upon Receipt °C	Total Chlorine mg/L	Free Chlorine mg/L	Total Coliform cfu/100mL	E. Coli Heterotrophic cfu/100mL	Plate Count (HPC) cfu/1mL
1: Analysis Start Date		---		---	01-Apr-14	01-Apr-14	01-Apr-14
2: Analysis Start Time		---		---	13:40	13:40	13:10
3: Analysis Approval Date		--		--	02-Apr-14	02-Apr-14	03-Apr-14
4: Analysis Approval Time		--		--	16:32	16:32	11:39
5: MAC		--		--	0	0	---
6: 26F9D RW RW-QMS: Raw Water 26F9D RW	31-Mar-14 08:00	10.0	---	---	0	0	33
7: 6712 NR DW DW1-QMS Daycare 6712 NR/DW	31-Mar-14 07:55	10.0	1.21	1.18	0	0	2
8: 13481 NR/DW DW43-QMS: Boys Bathroom Fountain 13481 NR/DW	31-Mar-14 07:45	10.0	1.36	1.18	0	0	1

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.



Carrie Greenlaw  
Project Specialist  
Environmental Services, Analytical