



SGS Canada Inc.

P.O. Box 4300 - 185 Concession St. Lakefield - Ontario - KOL 2H0 Phone: 705-652-2000 FAX: 705-652-6365

09-January-2014

OCWA-Trent Valley (Quinte Mohawk School)

Attn : James Taylor

Date Rec. : 07 January 2014 LR Report: CA16101-JAN14

Box 20157, 131 St. Paul St. Belleville, ON K8N 5V1,

Copy: #2

Phone: 613-962-5454 Fax:pdf-ID Plant

CERTIFICATE OF ANALYSIS Final Report

Table with 10 columns: Analysis, 1: Analysis Start Date, 2: Analysis Start Time, 3: Analysis Approval Date, 4: Analysis Approval Time, 5: MAC, 7: AO/OG, 8: MDL, 9: NR/TW Treated Water, 10: QMS Staff Room Tap. Rows include various water quality parameters like Temperature, Chlorine, pH, Alkalinity, etc.

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.

MAC - Maximum Acceptable Concentration AO/OG - Aesthetic Objective / Operational Guideline MDL - SGS Method Detection Limit

*Sodium > 20mg/L is an indicator of adverse water quality.

Note: Hydrogen Sulphide (H2S) results(s) reported below reporting limit based on corresponding Sulphide analysis.



SGS Canada Inc.

P.O. Box 4300 - 185 Concession St.
Lakefield - Ontario - K0L 2H0
Phone: 705-652-2000 FAX: 705-652-6365

**Not Reportable as per Chain of Custody
Works #: 1156**

Project : PO#017018

LR Report : CA16101-JAN14

Carrie Greenlaw
Carrie Greenlaw
Project Specialist
Environmental Services, Analytical