SGS Canada Inc.
P.O. Box 4300 - 185 Concession St.
Lakefield - Ontario - KOL 2HO
Phone: 705-652-2000 FAX: 705-652-6365

Not Reportable as per Chain of Custody
Works #: 1156

Project : PO#017018

12-September-2013

OCWA-Trent Valley (Quinte Mohawk School)
Attn : James Taylor

Box 20157, 131 St. Paul St.
Belleville, ON
K8N 5V1,

Phone: 613-962-5454
Fax:pdf-ID Plant

Date Rec. : 10 September 2013
LR Report: **CA16139-SEP13**

Copy: #1

CERTIFICATE OF ANALYSIS

Final Report

Sample ID	Sample Date & Time	Temperature Upon Receipt °C	Free Chlorine mg/L	Total Coliform cfu/100mL	E. Coli cfu/100mL	Heterotrophic Plate Count (HPC) cfu/1mL
1: Analysis Start Date		---	---	10-Sep-13	10-Sep-13	10-Sep-13
2: Analysis Start Time		---	---	15:55	15:55	15:30
3: Analysis Approval Date		---	---	12-Sep-13	12-Sep-13	12-Sep-13
4: Analysis Approval Time		---	---	14:09	14:09	15:07
5: MAC		---	---	0	0	---
6: 26F9D RW RW QMS: Raw Water Tap	09-Sep-13 11:09	15.0	---	0	0	23
7: 6712 NR/DW DW1 QMS Daycare	09-Sep-13 11:18	15.0	1.01	0	0	2
8: 13480 NR/DW DW3 QMS:Fountain Water; Girls Bathroom	09-Sep-13 11:27	15.0	0.95	0	0	1

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.

Carrie Greenlaw
Project Specialist
Environmental Services, Analytical

OnLine LIMS

0000017272

Data reported represents the sample submitted to SGS. Reproduction of this analytical report in full or in part is prohibited without prior written approval. Please refer to SGS General Conditions of Services located at http://www.sgs.com/terms_and_conditions_service.htm. (Printed copies are available upon request.)
Test method information available upon request. “Temperature Upon Receipt” is representative of the whole shipment and may not reflect the temperature of individual samples.