



SGS Canada Inc.

P.O. Box 4300 - 185 Concession St.
Lakefield - Ontario - KOL 2H0
Phone: 705-652-2000 FAX: 705-652-6365

**Not Reportable as per Chain of Custody
Works #: 1156**

Project : PO#017018

OCWA-Trent Valley (Quinte Mohawk School)

Attn : James Taylor

Box 20157, 131 St. Paul St.
Belleville, ON
K8N 5V1,

Phone: 613-962-5454
Fax:pdf-ID Plant

06-February-2014

**Date Rec. : 04 February 2014
LR Report: CA16177-FEB14**

Copy: #1

CERTIFICATE OF ANALYSIS

Final Report

| Sample ID | Sample Date & Temperature Time Upon Receipt °C | Free Chlorine mg/L | Total Coliform cfu/100mL | E. Coli cfu/100mL | Heterotrophic Plate Count (HPC) cfu/1mL |
|---|--|-----------------------|-----------------------------|----------------------|--|
| 1: Analysis Start Date | --- | --- | 04-Feb-14 | 04-Feb-14 | 04-Feb-14 |
| 2: Analysis Start Time | --- | --- | 15:25 | 15:25 | 14:50 |
| 3: Analysis Approval Date | -- | -- | 06-Feb-14 | 06-Feb-14 | 06-Feb-14 |
| 4: Analysis Approval Time | -- | -- | 13:10 | 13:10 | 13:10 |
| 5: MAC | -- | -- | 0 | 0 | --- |
| 6: 26F9D RW RW-QMS: Raw Water 26F9D RW | 03-Feb-14 08:16 | 8.0 | 0 | 0 | 89 |
| 7: 6712 NR DW DW1-QMS Daycare 6712 NR/DW | 03-Feb-14 08:52 | 8.0 | 1.24 | 0 | 0 |
| 8: 13480 NR/DW DW3-QMS: Fountain Water Girls Bathroom 13480 NR/DW | 03-Feb-14 09:01 | 8.0 | 1.33 | 0 | 0 |

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.


 Carrie Greenlaw
 Project Specialist
 Environmental Services, Analytical