



**SGS Canada Inc.**  
 P.O. Box 4300 - 185 Concession St.  
 Lakefield - Ontario - KOL 2H0  
 Phone: 705-652-2000 FAX: 705-652-6365

**Not Reportable as per Chain of Custody  
 Works #: 1156**

**Project : PO#017018**

10-July-2014

**OCWA-Trent Valley (Quinte Mohawk School)**

Attn : James Taylor

**Date Rec. : 08 July 2014  
 LR Report: CA16371-JUL14**

Box 20157, 131 St. Paul St.  
 Belleville, ON  
 K8N 5V1,

**Copy: #1**

Phone: 613-962-5454  
 Fax:pdf-ID Plant

## CERTIFICATE OF ANALYSIS

### Final Report

Sample ID	Sample Date & Time	Temperature Upon Receipt °C	Total Chlorine mg/L	Free Chlorine mg/L	Total Coliform cfu/100mL	E. Coli Heterotrophic cfu/100mL	Plate Count (HPC) cfu/1mL
1: Analysis Start Date		---	---	---	08-Jul-14	08-Jul-14	08-Jul-14
2: Analysis Start Time		---	---	---	13:00	13:00	12:35
3: Analysis Approval Date		--	--	--	10-Jul-14	10-Jul-14	10-Jul-14
4: Analysis Approval Time		--	--	--	10:33	10:33	11:46
5: MAC		--	--	--	0	0	---
6: 26F9D RW RW-QMS: Raw Water 26F9D RW	07-Jul-14 08:15	21.0	---	---	0	0	33
7: 6712 NR DW DW1-QMS Daycare 6712 NR/DW	07-Jul-14 08:10	21.0	1.47	1.32	0	0	1
8: 13481 NR DW DW3-Boys Washroom	07-Jul-14 08:00	21.0	0.87	0.81	0	0	20

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.

  
 Carrie Greenlaw  
 Project Specialist  
 Environmental Services, Analytical