



**SGS Canada Inc.**

P.O. Box 4300 - 185 Concession St.  
Lakefield - Ontario - K0L 2H0  
Phone: 705-652-2000 FAX: 705-652-6365

Not Reportable as per Chain of Custody  
Works #: 1156

Project : PO#017018

19-September-2013

**OCWA-Trent Valley (Quinte Mohawk School)**

Attn : James Taylor

Date Rec. : 17 September 2013  
LR Report: CA16438-SEP13

Box 20157, 131 St. Paul St.  
Belleville, ON  
K8N 5V1,

Copy: #1

Phone: 613-962-5454  
Fax:pdf-ID Plant

# CERTIFICATE OF ANALYSIS

## Final Report

Sample ID	Sample Date & Time	Temperature Upon Receipt °C	Free Chlorine mg/L	Total Coliform cfu/100mL	E. Coli cfu/100mL	Heterotrophic Plate Count (HPC) cfu/1mL
1: Analysis Start Date		---	---	17-Sep-13	17-Sep-13	17-Sep-13
2: Analysis Start Time		---	---	12:15	12:15	11:45
3: Analysis Approval Date		--	--	18-Sep-13	18-Sep-13	19-Sep-13
4: Analysis Approval Time		--	--	17:26	17:26	11:49
5: MAC		--	--	0	0	---
6: 26F9D RW QMS:Raw Water Tap RW	16-Sep-13 10:03	4.0	---	0	0	21
7: 6712 NR/DW DW1 QMS Daycare	16-Sep-13 10:15	4.0	1.12	0	0	1
8: 1F432 NR/DW DW3 QMS Fountain Waterfront Entrance	16-Sep-13 10:24	4.0	1.01	0	0	3

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.

Carrie Greenlaw  
Project Specialist  
Environmental Services, Analytical