



SGS Canada Inc.

P.O. Box 4300 - 185 Concession St. Lakefield - Ontario - KOL 2H0 Phone: 705-652-2000 FAX: 705-652-6365

14-April-2014

OCWA-Trent Valley (Quinte Mohawk School)

Attn : James Taylor

Date Rec. : 10 April 2014 LR Report: CA16557-APR14

Box 20157, 131 St. Paul St. Belleville, ON K8N 5V1,

Copy: #1

Phone: 613-962-5454 Fax:pdf-ID Plant

CERTIFICATE OF ANALYSIS Partial Report

Table with 11 columns: Analysis, 1: Analysis Start Date, 2: Analysis Start Time, 3: Analysis Approval Date, 4: Analysis Approval Time, 5: MAC Half, 6: MAC, 7: AO/OG, 8: MDL, 9: TW TW-QMS Treated Water NR/TW, 10: 1ec6a DW DW2-QMS Staff Room Tap NR/DW 1ec6a. Rows include various water quality parameters like Temperature, Chlorine, pH, Alkalinity, etc.



**SGS Canada Inc.**

P.O. Box 4300 - 185 Concession St.  
Lakefield - Ontario - K0L 2H0  
Phone: 705-652-2000 FAX: 705-652-6365

**Not Reportable as per Chain of Custody  
Works #: 1156**

**Project : PO#017018**

**LR Report : CA16557-APR14**

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.  
MAC - Maximum Acceptable Concentration  
Half MAC - Half of the Maximum Acceptable Concentration  
AO/OG - Aesthetic Objective / Operational Guideline  
MDL - SGS Method Detection Limit  
\*Sodium > 20mg/L is an indicator of adverse water quality.

---

*Carrie Greenlaw  
Project Specialist  
Environmental Services, Analytical*