



SGS Canada Inc.
 P.O. Box 4300 - 185 Concession St.
 Lakefield - Ontario - KOL 2H0
 Phone: 705-652-2000 FAX: 705-652-6365

**Not Reportable as per Chain of Custody
 Works #: 1156**

Project : PO#017018

20-March-2014

OCWA-Trent Valley (Quinte Mohawk School)

Attn : James Taylor

Date Rec. : 18 March 2014
LR Report: CA16789-MAR14

Box 20157, 131 St. Paul St.
 Belleville, ON
 K8N 5V1,

Copy: #1

Phone: 613-962-5454
 Fax:pdf-ID Plant

CERTIFICATE OF ANALYSIS

Final Report

Sample ID	Sample Date & Time	Temperature Upon Receipt °C	Total Chlorine mg/L	Free Chlorine mg/L	Total Coliform cfu/100mL	E. Coli Heterotrophic cfu/100mL	Plate Count (HPC) cfu/1mL
1: Analysis Start Date		---	---	---	18-Mar-14	18-Mar-14	18-Mar-14
2: Analysis Start Time		---	---	---	13:15	13:15	12:45
3: Analysis Approval Date		--	---	--	19-Mar-14	19-Mar-14	20-Mar-14
4: Analysis Approval Time		--	---	--	17:32	17:32	11:50
5: MAC		--	---	--	0	0	---
6: 26F9D RW RW-QMS: Raw Water Tap 26F9D RW	17-Mar-14 09:20	6.0	---	---	0	0	18
7: 6712 NR DW DW1-QMS Daycare 6712 NR/DW	17-Mar-14 09:30	6.0	1.80	1.59	0	0	1
8: 6711 NR DW DW3-QMS Kitchen Tap	17-Mar-14 09:40	6.0	1.56	1.48	0	0	2

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.


 Carrie Greenlaw
 Project Specialist
 Environmental Services, Analytical