



SGS Canada Inc.

P.O. Box 4300 - 185 Concession St.
Lakefield - Ontario - KOL 2H0
Phone: 705-652-2000 FAX: 705-652-6365

Project : PO#017018

March-07-13

OCWA-Trent Valley (Quinte Mohawk School)

Attn : James Taylor

Date Rec. : 05 March 2013
LR Report: CA17037-MAR13

Box 20157, 131 St. Paul St.
Belleville, ON
K8N 5V1,

Copy: #1

Phone: 613-962-5454
Fax:pdf-ID Plant

CERTIFICATE OF ANALYSIS

Final Report

Sample ID	Sample Date & Time	Temperature Upon Receipt °C	Free Chlorine mg/L	Total Coliform cfu/100mL	E. Coli cfu/100mL	Heterotrophic Plate Count (HPC) cfu/1mL
1: Analysis Start Date		---	---	05-Mar-13	05-Mar-13	05-Mar-13
2: Analysis Start Time		---	---	11:25	11:25	10:55
3: Analysis Approval Date		--	--	06-Mar-13	06-Mar-13	07-Mar-13
4: Analysis Approval Time		--	--	14:32	14:32	11:52
5: MAC		--	--	0	0	---
6: 26F9D RW QMS: Raw Water Tap	04-Mar-13 11:32	6.0	---	0	0	16
7: 1ec6a NR/DW QMS Staff Room Tap	04-Mar-13 12:14	6.0	1.22	0	0	0
8: 6712 NR/DW QMS Daycare	04-Mar-13 12:05	6.0	1.26	0	0	1

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.



Carrie Greenlaw
Project Specialist
Environmental Services, Analytical