



SGS Canada Inc.
 P.O. Box 4300 - 185 Concession St.
 Lakefield - Ontario - K0L 2H0
 Phone: 705-652-2000 FAX: 705-652-6365

**Not Reportable as per Chain of Custody
 Works #: 1156**

Project : PO#017018

17-July-2014

OCWA-Trent Valley (Quinte Mohawk School)

Attn : James Taylor

Date Rec. : 15 July 2014
LR Report: CA17086-JUL14

Box 20157, 131 St. Paul St.
 Belleville, ON
 K8N 5V1,

Copy: #1

Phone: 613-962-5454
 Fax:pdf-ID Plant

CERTIFICATE OF ANALYSIS

Partial Report

Sample ID	Sample Date & Time	Temperature Upon Receipt °C	Total Chlorine mg/L	Free Chlorine mg/L	Sodium mg/L
1: Analysis Start D		---	---	---	16-Jul-14
2: Analysis Start Ti		---	---	---	09:00
3: Analysis Approv		---	---	---	17-Jul-14
4: Analysis Approv		---	---	---	09:13
5: MAC		---	---	---	20*
7: AO/OG		--	---	---	200
8: MDL		--	---	---	0.01
9: TW TW-QMS T	14-Jul-14 08:05	21.0	1.68	1.54	33.2 MAC
10: 1ec6a DW D	14-Jul-14 08:27	21.0	1.43	1.27	33.5 MAC

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.

MAC - Maximum Acceptable Concentration

Half MAC - Half of the Maximum Acceptable Concentration

AO/OG - Aesthetic Objective / Operational Guideline

MDL - SGS Method Detection Limit

*Sodium > 20mg/L is an indicator of adverse water quality.

Note: Hydrogen Sulphide (H2S) results(s) reported below reporting limit based on corresponding Sulphide analysis.

MAC - (ADVERSE) Above Maximum Acceptable Concentration

Carrie Greenlaw
Project Specialist
Environmental Services, Analytical