



SGS Canada Inc.

P.O. Box 4300 - 185 Concession St. Lakefield - Ontario - KOL 2H0 Phone: 705-652-2000 FAX: 705-652-6365

21-July-2014

OCWA-Trent Valley (Quinte Mohawk School)

Attn : James Taylor

Date Rec. : 15 July 2014 LR Report: CA17086-JUL14

Box 20157, 131 St. Paul St. Belleville, ON K8N 5V1,

Copy: #2

Phone: 613-962-5454 Fax:pdf-ID Plant

CERTIFICATE OF ANALYSIS Final Report

Table with 11 columns: Analysis, 1: Analysis Start Date, 2: Analysis Start Time, 3: Analysis Approval Date, 4: Analysis Approval Time, 5: MAC, 6: Half MAC, 7: AO/OG, 8: MDL, 9: TW TW-QMS Treated Water NR/TW Room Tap NR/DW 1ec6a, 10: 1ec6a DW DW2-QMS Staff NR/DW 1ec6a. Rows include various water quality parameters like Temperature, Chlorine, pH, Alkalinity, etc.

SGS Canada Inc.

P.O. Box 4300 - 185 Concession St.
Lakefield - Ontario - K0L 2H0
Phone: 705-652-2000 FAX: 705-652-6365

Project : PO#017018

LR Report : CA17086-JUL14

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.

MAC - Maximum Acceptable Concentration

Half MAC - Half of the Maximum Acceptable Concentration

A0/OG - Aesthetic Objective / Operational Guideline

MDL - SGS Method Detection Limit

*Sodium > 20mg/L is an indicator of adverse water quality.

Note: Hydrogen Sulphide (H₂S) results(s) reported below reporting limit based on corresponding Sulphide analysis.

MAC - (ADVERSE) Above Maximum Acceptable Concentration, Sodium > 20mg/L is only reportable every 57 months as per applicable drinking water regulations.

Carrie Greenlaw

Project Specialist

Environmental Services, Analytical