

**SGS Canada Inc.**

P.O. Box 4300 - 185 Concession St.  
Lakefield - Ontario - KOL 2H0  
Phone: 705-652-2000 FAX: 705-652-6365

27-March-2014

**OCWA-Trent Valley (Quinte Mohawk School)**

Attn : James Taylor

Date Rec. : 25 March 2014  
LR Report: CA17121-MAR14

Box 20157, 131 St. Paul St.  
Belleville, ON  
K8N 5V1,

Copy: #1

Phone: 613-962-5454  
Fax:pdf-ID Plant

## CERTIFICATE OF ANALYSIS

### Final Report

Sample ID	Sample Date & Time	Temperature Upon Receipt °C	Total Chlorine mg/L	Free Chlorine mg/L	Total Coliform cfu/100mL	E. Coli cfu/100mL	Heterotrophic Plate Count (HPC) cfu/1mL
1: Analysis Start Date		---			25-Mar-14	25-Mar-14	25-Mar-14
2: Analysis Start Time		---			13:10	13:10	12:35
3: Analysis Approval Date		--			27-Mar-14	27-Mar-14	27-Mar-14
4: Analysis Approval Time		--			11:35	11:35	11:35
5: MAC		--			0	0	---
6: 26F9D RW QMS: Raw Water Tap	24-Mar-14 09:05	8.0	---	---	0	0	18
7: 6712 NR DW QMS Daycare	24-Mar-14 09:25	8.0	1.53	1.32	0	0	0
8: 13480 NR/DW Fountain Girls Washroom	24-Mar-14 09:15	8.0	1.14	0.92	0	0	4

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.

  
 Carrie Greenlaw  
 Project Specialist  
 Environmental Services, Analytical