

SGS Canada Inc.

P.O. Box 4300 - 185 Concession St.
Lakefield - Ontario - KOL 2H0
Phone: 705-652-2000 FAX: 705-652-6365

05-September-2014

OCWA-Trent Valley (Quinte Mohawk School)

Attn : James Taylor

Date Rec. : 03 September 2014
LR Report: CA17504-SEP14

Box 20157, 131 St. Paul St.
Belleville, ON
K8N 5V1,

Copy: #1

Phone: 613-962-5454
Fax:pdf-ID Plant

CERTIFICATE OF ANALYSIS

Final Report

Sample ID	Sample Date & Temperature Time Upon Receipt °C	Total Chlorine mg/L	Free Chlorine mg/L	Total Coliform cfu/100mL	E. Coli Heterotrophic cfu/100mL	Plate Count (HPC) cfu/1mL
1: Analysis Start Date	---	---	---	03-Sep-14	03-Sep-14	03-Sep-14
2: Analysis Start Time	---	---	---	11:20	11:20	10:55
3: Analysis Approval Date	--	---	--	04-Sep-14	04-Sep-14	05-Sep-14
4: Analysis Approval Time	--	---	--	13:47	13:47	09:56
5: MAC	--	---	--	0	0	---
6: 26F9D RW RW-QMS: Raw Water 26F9D RW	02-Sep-14 08:00	19.0	---	0	0	8
7: 6712 NR DW DW1-QMS Daycare 6712 NR/DW	02-Sep-14 08:15	19.0	1.60	1.45	0	6
8: 1EC6A NR DW DW2-QMS Staff Room Tap 1EC6A NR/DW	02-Sep-14 08:05	19.0	1.66	1.35	0	1

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.


 Carrie Greenlaw
 Project Specialist
 Environmental Services, Analytical