



Not Reportable as per Chain of Custody
Works #: 1156

Project : PO#017018

SGS Canada Inc.

P.O. Box 4300 - 185 Concession St.
Lakefield - Ontario - KOL 2H0
Phone: 705-652-2000 FAX: 705-652-6365

14-March-2014

OCWA-Trent Valley (Quinte Mohawk School)

Attn : James Taylor

Date Rec. : 11 March 2014
LR Report: CA17577-MAR14

Box 20157, 131 St. Paul St.
Belleville, ON
K8N 5V1,

Copy: #1

Phone: 613-962-5454
Fax:pdf-ID Plant

CERTIFICATE OF ANALYSIS

Final Report

Sample ID	Sample Date & Time	Temperature Upon Receipt °C	Total Chlorine mg/L	Free Chlorine mg/L	Total Coliform cfu/100mL	E. Coli cfu/100mL	Heterotrophic Plate Count (HPC) cfu/1mL
1: Analysis Start Date		---	---	---	11-Mar-14	11-Mar-14	11-Mar-14
2: Analysis Start Time		---	---	---	16:15	16:15	15:45
3: Analysis Approval Date		--	---	--	13-Mar-14	13-Mar-14	13-Mar-14
4: Analysis Approval Time		--	---	--	09:12	09:12	16:21
5: MAC		--	---	--	0	0	---
6: 26F9D RW RW-QMS: Raw Water 26F9D RW	10-Mar-14 09:15		10.0	---	0	0	63
7: 6712 NR DW DW1-QMS Daycare 6712 NR/DW	10-Mar-14 09:30		10.0	1.59	1.43	0	0
8: 1F432 NR/DW DW3-QMS: Fountain Water Front Entrance 1F432 NR/DW	10-Mar-14 09:45		10.0	1.23	1.14	0	0

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.



Carrie Greenlaw
Project Specialist
Environmental Services, Analytical