



Not Reportable as per Chain of Custody
Works #: 1156

Project : PO#017018

SGS Canada Inc.

P.O. Box 4300 - 185 Concession St.
Lakefield - Ontario - KOL 2H0
Phone: 705-652-2000 FAX: 705-652-6365

21-February-2014

OCWA-Trent Valley (Quinte Mohawk School)

Attn : James Taylor

Date Rec. : 19 February 2014
LR Report: CA17592-FEB14

Box 20157, 131 St. Paul St.
Belleville, ON
K8N 5V1,

Copy: #1

Phone: 613-962-5454
Fax:pdf-ID Plant

CERTIFICATE OF ANALYSIS

Final Report

Sample ID	Sample Date & Temperature Time Upon Receipt °C	Total Chlorine mg/L	Free Chlorine mg/L	Total Coliform cfu/100mL	E. Coli cfu/100mL	Heterotrophic Plate Count (HPC) cfu/1mL
1: Analysis Start Date	---	---	---	19-Feb-14	19-Feb-14	19-Feb-14
2: Analysis Start Time	---	---	---	14:45	14:45	14:10
3: Analysis Approval Date	--	---	--	20-Feb-14	20-Feb-14	21-Feb-14
4: Analysis Approval Time	--	---	--	14:34	14:34	12:22
5: MAC	--	---	--	0	0	---
6: 26F9D RW RW-QMS: Raw Water 26F9D RW	18-Feb-14 09:15	8.0	---	0	0	53
7: 6712 NR DW DW1-QMS Daycare 6712 NR/DW	18-Feb-14 09:00	8.0	1.28	1.15	0	0
8: 13480 NR/DW DW3-QMS: Fountain Water Girls Bathroom 13480 NR/DW	18-Feb-14 09:07	8.0	1.26	1.10	0	0

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.



Carrie Greenlaw
Project Specialist
Environmental Services, Analytical