



SGS Canada Inc.

P.O. Box 4300 - 185 Concession St.
Lakefield - Ontario - KOL 2H0
Phone: 705-652-2000 FAX: 705-652-6365

August-09-13

OCWA-Trent Valley (Quinte Mohawk School)

Attn : James Taylor

Date Rec. : 07 August 2013
LR Report: CA18171-AUG13

Box 20157, 131 St. Paul St.
Belleville, ON
K8N 5V1,

Copy: #1

Phone: 613-962-5454
Fax:pdf-ID Plant

CERTIFICATE OF ANALYSIS

Final Report

Sample ID	Sample Date & Time	Temperature Upon Receipt °C	Free Chlorine mg/L	Total Coliform cfu/100mL	E. Coli cfu/100mL	Heterotrophic Plate Count (HPC) cfu/1mL
1: Analysis Start Date		---	---	07-Aug-13	07-Aug-13	07-Aug-13
2: Analysis Start Time		---	---	13:40	13:40	13:20
3: Analysis Approval Date		--	--	08-Aug-13	08-Aug-13	09-Aug-13
4: Analysis Approval Time		--	--	15:41	15:41	12:30
5: MAC		--	--	0	0	---
6: 26F9D RW-QMS: Raw Water Tap RW	06-Aug-13 12:02	14.0	---	0	0	15
7: 1EC6A NR DW-QMS Staff Room Tap DW2	06-Aug-13 12:14	14.0	1.38	0	0	0
8: 6712 NR DW-QMS Daycare DW1	06-Aug-13 12:27	14.0	1.31	0	0	2

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.



Carrie Greenlaw
Project Specialist
Environmental Services, Analytical