

SGS Canada Inc.

P.O. Box 4300 - 185 Concession St.
Lakefield - Ontario - KOL 2H0
Phone: 705-652-2000 FAX: 705-652-6365

31-October-2013

OCWA-Trent Valley (Quinte Mohawk School)

Attn : James Taylor

Date Rec. : 29 October 2013

LR Report: CA18209-OCT13

Box 20157, 131 St. Paul St.
Belleville, ON
K8N 5V1,

Copy: #1

Phone: 613-962-5454
Fax:pdf-ID Plant

CERTIFICATE OF ANALYSIS

Final Report

Sample ID	Sample Date & Time	Temperature Upon Receipt °C	Free Chlorine mg/L	Total Coliform cfu/100mL	E. Coli cfu/100mL	Heterotrophic Plate Count (HPC) cfu/1mL
1: Analysis Start Date		---	---	29-Oct-13	29-Oct-13	29-Oct-13
2: Analysis Start Time		---	---	17:15	17:15	16:35
3: Analysis Approval Date		--	--	30-Oct-13	30-Oct-13	31-Oct-13
4: Analysis Approval Time		--	--	16:31	16:31	13:57
5: MAC		--	--	0	0	0
6: 26F9D RW RW-QMS: Raw Water Tap	28-Oct-13 08:44	10.0	---	0	0	17
7: 6712 NR DW DW1-QMS Daycare	28-Oct-13 08:34	10.0	0.99	0	0	10
8: 1F432 NR DW DW3-Front Fountain	28-Oct-13 08:56	10.0	0.56	0	0	37

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.


 Carrie Greenlaw
 Project Specialist
 Environmental Services, Analytical