



**SGS Canada Inc.**

P.O. Box 4300 - 185 Concession St.  
Lakefield - Ontario - K0L 2H0  
Phone: 705-652-2000 FAX: 705-652-6365

Not Reportable as per Chain of Custody  
Works #: 1156

Project : PO#017018

July-15-13

**OCWA-Trent Valley (Quinte Mohawk School)**

Attn : James Taylor

Date Rec. : 12 July 2013  
LR Report: CA18227-JUL13

Box 20157, 131 St. Paul St.  
Belleville, ON  
K8N 5V1,

Copy: #1

Phone: 613-962-5454  
Fax:pdf-ID Plant

# CERTIFICATE OF ANALYSIS

## Final Report

Sample ID	Sample Date & Time	Temperature Upon Receipt °C	Free Chlorine mg/L	Total Coliform cfu/100mL	E. Coli cfu/100mL	Heterotrophic Plate Count (HPC) cfu/1mL
1: Analysis Start Date		---	---	12-Jul-13	12-Jul-13	12-Jul-13
2: Analysis Start Time		---	---	11:40	11:40	11:10
3: Analysis Approval Date		--	--	15-Jul-13	15-Jul-13	15-Jul-13
4: Analysis Approval Time		--	--	10:05	10:05	10:05
5: MAC		--	--	0	0	---
6: 6712 NR/DW QMS Daycare DW DW1	11-Jul-13 10:23	18.0	1.14	0	0	1
7: 13480 NR/DW QMS: Fountain Water & Girls Bathroom DW DW3	11-Jul-13 10:30	18.0	0.89	0	0	2

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.

Carrie Greenlaw  
Project Specialist  
Environmental Services, Analytical