



SGS Canada Inc.

P.O. Box 4300 - 185 Concession St.
Lakefield - Ontario - KOL 2H0
Phone: 705-652-2000 FAX: 705-652-6365

July-24-13

OCWA-Trent Valley (Quinte Mohawk School)

Attn : James Taylor

Date Rec. : 17 July 2013
LR Report: CA18520-JUL13

Box 20157, 131 St. Paul St.
Belleville, ON
K8N 5V1,

Copy: #1

Phone: 613-962-5454
Fax:pdf-ID Plant

CERTIFICATE OF ANALYSIS

Final Report

Sample ID	Sample Date & Time	Temperature Upon Receipt °C	Free Chlorine mg/L	Total Coliform cfu/100mL	E. Coli cfu/100mL	Heterotrophic Plate Count (HPC) cfu/1mL	Sodium mg/L
1: Analysis Start Date		---	---	17-Jul-13	17-Jul-13	17-Jul-13	23-Jul-13
2: Analysis Start Time		---	---	11:45	11:45	11:25	10:57
3: Analysis Approval Date		---	---	18-Jul-13	18-Jul-13	19-Jul-13	24-Jul-13
4: Analysis Approval Time		---	---	14:39	14:39	11:09	10:28
5: MAC		---	---	0	0	---	*20
7: AO/OG		---	---	---	---	---	200
8: MDL		---	---	---	---	---	0.01
9: 1EC6A NR/DW QMS:Staff Room Tap	16-Jul-13 10:18	20.0	1.24	0	0	6	---
10: 1F430 NR/DW QMS:Classroom #18	16-Jul-13 10:14	20.0	1.31	0	0	0	---
11: 26F90 NR/DW QMS:Raw Water Tap	16-Jul-13 09:48	20.0	---	---	---	---	25.3

Total and/or Free Residual Chlorine was not analyzed by SGS Environmental Services.
MAC - Maximum Acceptable Concentration
AO/OG - Aesthetic Objective / Operational Guideline
MDL - SGS Method Detection Limit
*Sodium > 20mg/L is an indicator of adverse water quality.


Carrie Greenlaw
Project Specialist
Environmental Services, Analytical